

REMARKS

Applicant attached revised drawings for the Examiner's approval. In the "Replacement Sheet," Figure 1 is amended to change the annotation within the box identified with reference number 23 from "CPU INTERFACE" to "LCD INTERFACE". This is an obvious typographical error.

As can be seen in Figure 1, the interface 23 is located between the Memory Cell Array 22 and the LCD Panel 30. As such, the interface 23 is clearly an "LCD INTERFACE". Further support for this amendment can be found throughout the Detailed Description where the LCD interface is identified with the reference number 23.

Prompt and favorable consideration of this amendment is respectfully requested. If the Examiner believes that personal communication will expedite prosecution of this application, the Examiner is invited to telephone the undersigned at (248) 641-1600.

Respectfully submitted,

Dated: July 19, 2004

By: 

G. Gregory Schivley
Reg. No. 27,382
Bryant E. Wade
Reg. No. 40,344

HARNESS, DICKEY & PIERCE, P.L.C.
P.O. Box 828
Bloomfield Hills, Michigan 48303
(248) 641-1600

[BEW/cmh]